Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Harry Walker No. 19 AUM Site

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.599.1111

January 2011

Part I	Site Identification, Location and Status					
Site Names and ID numbers as applicable						
Mine ID:	547					
Map ID:	W58					
CERCLIS:	NNN000909124					
Navajo Abandoned Mine Land Reclamation Program: None						
Local name / Aliases: None						
Chapter and local area: Cameron Chapter						
County: Coc	Coconino State: Arizona					
Lat/Long: 35.8374447491 N / -111.390827992 W						
Nearby road	and highway:	Highway 89	Local Post O	ffice: Cameron, AZ		
Surface Land Status: check one or more and provide ownership and contact information below						
Tribal Trust Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land			
Subsurface Mineral Rights:						
No information on subsurface mineral rights ownership was found in the EPA/AUM Database						
Claim and operator information:						
The mine site surface land status is classified as Tribal Trust Land. No additional ownership / lease information was identified in the EPA/AUM database.						
Number of residential structures within 200 feet of mine: None						
Estimated volume of mine waste onsite: 1.5 yd ³						

Part II Summary of radiological readings

Highest gamma radiation measurement:

545,900 counts per minute (cpm)

Describe any other radiological measurements:


A total of 2,990 gamma radiation measurements were collected from the mine site, ranging from 9,014 cpm to 545,900 cpm. The measurements collected at the waste pile were found at a maximum level of approximately 550,000 cpm, and within the reclamation cap drainage at a maximum level of approximately 150,000 cpm. The measurements are represented in Figures 1 and 2.

Background Readings: 13,338 cpm

Background Average: 13,338 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 2990

 Minimum:
 9014,00000

 Maximum:
 545900,00000

 Sum:
 100393742,00000

 Mean:
 33576,50234

 Median:
 20233,50000

 Standard Deviation:
 54564,21079

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: No Waste Pile onsite: No

NAMLRP Project Number: None

NAMLRP Mine features: None

The following information was obtained from field observations collected during the 2010 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed	reclamation	work and	ctatuc.
COUNCI VCU	i cciainauvii	wui K anu	Status.

Adits

None

Waste Piles

Waste pile 3' x 8' x 1.5', yellow-brown fine material

Pits

None

Shafts

None

Other Debris and Mine Features

Reclamation cap, site has been reclaimed but exposed material in southern area due to erosion

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: Little Colorado River Basin approximately 1 mi E of the site

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Harry Walker No. 19 mine consists of an area of 26,732.27 m². No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity? Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? Yes

Structures:

Were any structures observed within 200 feet of the mine?

No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1. Harry Walker No. 19 mine site



Photo 2. Harry Walker No. 19 mine site, exposed ore



Photo 3. Harry Walker No. 19 mine site, waste pile



Photo 4. Harry Walker No. 19 mine site, elevated gamma radiation readings


Name:

Part VII Contacts Reports and Information

Stanley Edison (928) 871-6861

Eugene Esplain (928) 871-7331	
Title or official role (if any) Navajo EPA Superfund Program	
AddressPO Box 2946, Window Rock, AZ 86515	
Information provided Lead Regulatory Agency	
Name	
Title or official role (if any)	
Address	
Telephone number	
Information provided	
Name	
Title or official role (if any)	_
Telephone number	_
Information provided	
Name	
Title or official role (if any)	_
Telephone number	_
Information provided	

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Harry Walker No. 19 (547)
Cameron Chapter, Navajo Nation



- < 2X Backgound</p>
- > 2X Background


Gamma survey conducted 11/2010 Measured as counts per minute (cpm)

Average background 13,338 cpm





Figure 2 - Gamma Radiation Measurements Harry Walker No. 19 (547) Cameron Chapter, Navajo Nation



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- **2**0,000 50,000
- 50,000 100,000
- > 100,000



Gamma survey conducted 11/2010 Measured as counts per minute (cpm)

Average background 13,338 cpm

